







CAPABILITY STATEMENT – ENVIRONMENTAL SITE ASSESSMENTS

KEY STAFF

Vice President – Environmental Services David Cutlip

dcutlip@markosky.com

Environmental Services Division Manager Jason Harkcom jharkcom@markosky.com

Environmental Sciences Department Manager

abrehm@markosky.com

Ashley Brehm

Environmental Scientist Elliott Mazur

emazur@markosky.com

CORE COMPETENCIES & SERVICES

THE MARKOSKY ENGINEERING GROUP, INC. is qualified to provide Phase I ESAs (ASTM E1527-13), Phase II ESAs (ASTM E1903-11), and Transaction Screens (ASTM E1528-14) for commercial real estate acquisitions. Additional services include waste site evaluations for government entities including DOT's.

We hold the following professional Registrations:

- Professional Geologist
- Asbestos Inspector
- Lead Paint Inspector

Our core Environmental Site Assessment services include the following:


- Environmental Site Assessment Phase I & II ESA's
- Environmental Investigation Drilling
- Long Term Monitoring & Sampling of sites
- Asbestos Inspections
- Water Well Abandonment
- Groundwater Monitoring
- Lead Based Paint Sampling

Related Services

- Wetland Evaluations
- Threatened & Endangered Species Coordination
- Stream and Surface Water Surveys

Markosky is qualified to perform DOT Waste Site Evaluations, Phase I ESAs (ASTM E1527-13), Transaction Screens (ASTM E1528-14) for commercial real estate acquisitions for Phase II ESAs (ASTM E1903-11).









WVUCP DBE (WBE) C04725-00

NAICS Codes:

541620, 541330, 541990, 237110, 541720

UEI:

EEMAGUCMLYG1

CAGE: 50GY5



WWW.MARKOSKY.COM

304.719.4778

PAST PERFORMANCE

US 119 Youngwood ReconstructionClient: PennDOT District 12-0

Services

- Phase II Environmental Investigation
- ❖ Soil & Groundwater Sampling
- District / utility Coordination

Chartiers Bridge #53

Client: Washington County Planning Commission

Services

- Asbestos Inspection
- ❖ Lead Based Paint Survey
- Phase I Environmental Site Assessment

Former Plastics Warehouse Client: Energy Client

Services

Phase I Environmental Site Assessment



US 119 Youngwood Reconstruction Westmoreland County, PA



US 119 Youngwood Reconstruction Westmoreland County, PA



Chartiers Bridge #53 Washington County, PA



Former Plastics Warehouse Little Hocking, OH

